

--TOWN OF BOLTON--
FYFESHIRE POND DAM
PHASE I
INSPECTION / EVALUATION REPORT



Dam Name: Fyfeshire Dam, also known as Fish Pond Dam
State Dam ID#: 3-14-34-2
NID ID#: MA01512
Owner: Town of Bolton Conservation Commission
Owner Type: Bolton, MA
Town: Municipal
Consultant: AMEC Earth & Environmental Inc.
Date of Inspection: 7/17/2008

EXECUTIVE SUMMARY

- *Fyfeshire Dam (AKA Fish Pond Dam), Bolton, MA*
- *July 17, 2008*
- *AMEC Earth & Environmental, Inc.*
- *Dam Condition: Unsafe*
- *Major Deficiencies: Failing Spillway, Bulging Embankment, Lack of Documentation.*

In 1878 William E. Fyfe of Bolton owned the property where Fyfeshire Dam is currently located. He had built a Button Factory Mill, and the associated Fyfeshire Dam, with the latter impounding water to supply power for the Button Shop. In 1880, the Button Shop burned down and was not rebuilt. Currently the Dam is being used for recreational and conservatory purposes.

The dam is earth-filled between stacked-stone walls with a cast-in-place concrete spillway about midway along the dam's length. The downstream face of the dam is near-vertical stacked stone. The western end of the stacked stone downstream face has a noticeable bulge. A few large trees are growing at the toe of the downstream face. The upstream face of the dam is sloped approximately 2 (horizontal) to 1 (vertical) and covered with stone facing. The abutments and toe of the downstream embankment have large trees growing upon them.

The dam and spillway have a footpath crossing the crest and a steel walkway, with handrail, across the spillway. Within the last eight to ten years the spillway was modified by adding an approximately three feet high, concrete sill within the spillway. Likewise, two small concrete walls have been added on the left side of the spillway to slow erosion that is ongoing behind the left wall of the spillway. Both vertical walls of the spillway have horizontal cracks about ½ up from the floor. The cracks extend the full length of the spillway and appear to be completely through the spillway walls. There is significant deflection of the left (east) spillway wall toward the center of the spillway. The type and size of aggregate exposed in the crack and the lack of reinforcing steel appears to be consistent with concrete produced in the latter part of the 19th century.

The spillway is partially clogged with branches and mud that appear to have accumulated due to storm flows. In the past, the pond has been home to beavers; however, there is little fresh sign of beaver activity. A 15-inch diameter corrugated polyethylene pipe and screened inlet was installed from the pool in front of the dam extending slightly past the spillway, atop the concrete sill, to bypass the accumulated debris or beaver dam. The pipe and inlet were installed within the last three years according to the limited records.

In general, the overall condition of the Fyfeshire Dam (a.k.a. Fish Pond Dam) is Unsafe. The dam was found to have structural deficiencies in the embankments due to wall instability, large tree growth, and failing concrete spillway.

The spillway and embankments will require immediate replacement or significant repairs to remain in service.

Dam Evaluation Summary Detail Sheet

1. NID ID: MA01512	2. Dam Name: Fish Pond Dam (AKA Fyfeshire Dam)	3. Dam Location: Bolton, MA
4. Inspection Date: 7/17/2008	5. Last Insp. Date: unknown	6. Next Inspection: 7/16/2013
7. Inspector: D. E. Tate	8. Consultant: AMEC Earth & Environmental, Inc.	
9. Hazard Code: Significant (Class 2)	10. Insp. Frequency: Significant-5 Yrs.	11. Insp. Condition: Unsafe
E1. Design Methodology:	1	E7. Low-Level Discharge Capacity: 1
E2. Level of Maintenance:	2	E8. Low-Level Outlet Physical Condition: 1
E3. Emergency Action Plan:	2	E9. Spillway Design Flood Capacity:
E4. Embankment Seepage:	3	E10. Overall Physical Condition of the Dam: 1
E5. Embankment Condition:	2	E11. Estimated Repair Cost (in thousand \$):
E6. Concrete Condition:	1	

Evaluation Description

E1: DESIGN METHODOLOGY

1. Unknown Design – no design records available
3. Some standard design features
5. State of the art design – design records available

E2: LEVEL OF MAINTENANCE

1. No evidence of maintenance, no O&M manual
2. Very little maintenance, no O&M manual
3. Some level of maintenance and standard procedures
4. Adequate level of maintenance and standard procedures
5. Detailed maintenance plan that is executed

E3: EMERGENCY ACTION PLAN

1. No plan or idea of what to do in the event of an emergency
2. Some idea but no written plan
3. No formal plan but well thought out
4. Available written plan that needs updating
5. Detailed, updated written plan available and filed with MADCR

E4: EMBANKMENT SEEPAGE

1. Severe piping and/or seepage with no monitoring
2. Evidence of monitored piping and seepage
3. No piping but uncontrolled seepage
4. Controlled seepage
5. No seepage or piping

E5: EMBANKMENT CONDITION

1. Severe erosion and/or large trees
2. Significant erosion or significant woody vegetation
3. Brush and exposed embankment soils, or moderate erosion
4. Unmaintained grass, rodent activity and maintainable erosion
5. Well maintained healthy uniform grass cover

E6: CONCRETE CONDITION

1. Major cracks, misalignment, discontinuities causing leaks, seepage or stability concerns
2. Cracks with misalignment inclusive of transverse cracks with no misalignment
3. Significant longitudinal cracking and minor transverse cracking
4. Spalling and minor surface cracking
5. No apparent deficiencies

E7: LOW LEVEL OUTLET DISCHARGE CAPACITY

1. No low level outlet
2. Outlet with insufficient drawdown capacity
3. Inoperable gate with potentially sufficient drawdown capacity
4. Operable gate with sufficient drawdown capacity
5. Operable gate with capacity greater than necessary

E8: LOW LEVEL OUTLET PHYSICAL CONDITION

1. Outlet inoperative needs replacement, non-existent or inaccessible
2. Outlet inoperative needs repair
3. Outlet operable but needs repair
4. Outlet operable but needs maintenance
5. Outlet and operator operable and well maintained

E9: SPILLWAY DESIGN FLOOD CAPACITY

1. 0 - 20% of the SDF
2. 21- 40% of the SDF
3. 41- 60% of the SDF
4. 61- 80% of the SDF
5. 81- 100% of the SDF

E10: OVERALL PHYSICAL CONDITION OF THE DAM

1. **UNSAFE** – Major structural, operational, and maintenance deficiencies exist under normal operating conditions
2. **POOR** - Significant structural, operation and maintenance deficiencies are clearly recognized under normal loading conditions
3. **FAIR** - Significant operational and maintenance deficiencies, no structural deficiencies. Potential deficiencies exist under unusual loading conditions that may realistically occur. Can be used when uncertainties exist as to critical parameters
4. **SATISFACTORY** - Minor operational and maintenance deficiencies. Infrequent hydrologic events would probably result in deficiencies.
5. **GOOD** - No existing or potential deficiencies recognized. Safe performance is expected under all loading including SDF

E11: ESTIMATED REPAIR COST

Estimation of the total cost to address all identified structural, operational, maintenance deficiencies. Cost shall be developed utilizing standard estimating guides and procedures

Changes/Deviations to Database Information since last inspection

No previous inspection was available. Town records show that the spillway was inspected by an engineer (GOLDSMITH, PREST & RINGWALL, INC.) in January, 1998, who recommended its replacement. E9 Spillway Capacity - the capacity of the spillway relative to the design storm is unknown.

PREFACE

The assessment of the general condition of the dam is based upon available data and visual inspections. Detailed investigations and analyses involving topographic mapping, subsurface investigations, testing and detailed computational evaluations are beyond the scope of this report.

In reviewing this report, it should be realized that the reported condition of the dam is based on observations of field conditions at the time of inspection, along with data available to the inspection team. In cases where an impoundment is lowered or drained prior to inspection, such action, while improving the stability and safety of the dam, removes the normal load on the structure and may obscure certain conditions, which might otherwise be detectable if inspected under the normal operating environment of the structure.

It is critical to note that the condition of the dam depends on numerous and constantly changing internal and external conditions, and is evolutionary in nature. It would be incorrect to assume that the present condition of the dam will continue to represent the condition of the dam at some point in the future. Only through continued care and inspection can there be any chance that unsafe conditions be detected.



Licensed Professional's Signature*

* 302 CMR 10.00 requires inspecting engineers to be Commonwealth of Massachusetts Registered Professional Engineers with a **Civil engineering license** with experience in dam safety inspections and engineering. The Department will also accept a Commonwealth of Massachusetts Registered Professional **Structural or Sanitary engineering license stamp**, provided the Registered Professional Engineer has experience in the field of dam engineering and inspection.

Douglas Tate, PE
Massachusetts License No.: 40908
Geotechnical Engineer
AMEC Earth and Environmental, Inc.




TABLE OF CONTENTS

Page No.

EXECUTIVE SUMMARY

PREFACE

SECTION 1	1
1.0 DESCRIPTION OF PROJECT.....	1
1.1 General.....	1
1.1.1 Authority	1
1.1.2 Purpose of Work	1
1.1.3 Definitions	1
1.2 Description of Project	1
1.2.1 Location	1
1.2.2 Owner/Operator	2
1.2.3 Purpose of the Dam.....	2
1.2.4 Description of the Dam and Appurtenances	2
1.2.5 Operations and Maintenance.....	2
1.2.6 DCR Size Classification	3
1.2.7 DCR Hazard Classification.....	3
1.3 Pertinent Engineering Data.....	3
1.3.1 Drainage Area	3
1.3.2 Reservoir	3
1.3.3 Discharges at the Dam Site	3
1.3.4 General Elevations (feet, measured from the bottom of the spillway)	4
1.3.5 Main Spillway	4
1.3.6 Other Information	4
1.3.7 Design or As-built (Record).....	4
1.3.8 Operating Records	4
SECTION 2	5
2.0 INSPECTION.....	5
2.1 Visual Inspection	5
2.1.1 General Findings.....	5
2.1.2 Dam.....	5
2.1.2.1 Abutments.....	5
2.1.2.2 Upstream Face	5
2.1.2.3 Crest.....	5
2.1.2.4 Downstream Face	6
2.1.2.5 Drains	6
2.1.2.6 Instrumentation.....	6
2.1.2.7 Access Roads and Gates	6
2.1.3 Appurtenant Structures	6
2.1.3.1 Primary Spillway	6
2.1.3.2 Low Level Outlets	7

2.1.3.3	Auxiliary/Emergency Spillway	7
2.1.4	Downstream Area	7
2.1.5	Reservoir Area	7
2.2	Caretaker Interview	7
2.3	Operation and Maintenance Procedures	8
2.3.1	Operational Procedures	8
2.3.2	Maintenance of Dam and Operating Facilities	8
2.4	Emergency Warning System	8
2.5	Hydrologic/Hydraulic Data	8
2.6	Structural Stability/Overtopping Potential.....	8
2.6.1	Structural Stability	8
2.6.2	Overtopping Potential	8
SECTION 3	9
3.0	ASSESSMENTS AND RECOMMENDATIONS	9
3.1	Assessments.....	9
3.2	Studies and Analyses	9
3.3	Yearly Recommendations.....	9
3.4	Recommendations, Maintenance, and Minor Repairs.....	9
3.5	Remedial Measures	9
3.6	Alternatives	9
3.7	Opinion of Probable Construction Costs	10

FIGURES

Figure 1: Locus Plan

Figure 2: Site Sketch

APPENDICES

Appendix A: Photographs

Appendix B: Inspection Checklist

Appendix C: Previous Reports and References

Appendix D: Definitions

SECTION 1

1.0 DESCRIPTION OF PROJECT

1.1 General

1.1.1 Authority

The Town of Bolton has retained AMEC Earth & Environmental to perform a visual inspection and develop a Phase I Report of conditions for the Fyfeshire Dam, also known as Fish Pond Dam, in Bolton, Massachusetts. This inspection and report were performed in accordance with MGL Chapter 253, Sections 44-50 of the Massachusetts General Laws as amended by Chapter 330 of the Acts of 2002.

1.1.2 Purpose of Work

The purpose of this investigation is to inspect and evaluate the present condition of the dam and appurtenant structures in accordance with 302 CMR10.07 to provide information that will assist in both prioritizing dam repair needs and planning/conducting maintenance and operation.

The investigation is divided into four parts: 1) obtain and review available reports, investigations, and data previously submitted to the owner pertaining to the dam and appurtenant structures; 2) perform a visual inspection of the site; 3) evaluate the status of an emergency action plan for the site and; 4) prepare and submit a final report presenting the evaluation of the structure, including recommendations and remedial actions, and opinion of probable costs.

1.1.3 Definitions

To provide the reader with a better understanding of the report, definitions of commonly used terms associated with dams are provided in Appendix D. Many of these terms may be included in this report. The terms are presented under common categories associated with dams which include: 1) orientation; 2) dam components; 3) size classification; 4) hazard classification; and 5) miscellaneous.

1.2 Description of Project

1.2.1 Location

The dam is located in the Fyfeshire Conservation Area, a property owned and maintained by the Town of Bolton Conservation Commission. It is located off of Watoquadoc Hill Road in the southwestern portion of Bolton, at latitude 42.41530, longitude -71.64902. The dam is on the south side of Fyfeshire Pond with the upstream face of the dam facing north.

1.2.2 Owner/Operator

	Dam Owner	Dam Caretaker
Name	Town of Bolton Conservation Commission	Town of Bolton Conservation Commission, CO Carol Gumbart
Mailing Address	Town Hall, 663 Main Street	Town Hall, 663 Main Street
Town	Bolton, MA 01740	Bolton, MA 01740
Daytime Phone	978-779-3304	508-877-2297
Emergency Phone		
Email Address	concom@townofbolton.com	concom@townofbolton.com

1.2.3 Purpose of the Dam

In 1878 William E. Fyfe of Bolton owned the property where Fyfeshire Dam is located. He had built The Button Factory Mill and rented it to McNeal, Plummer & Company. The Factory was very small and employed 3 people besides the owner. The Fyfeshire Dam was used as an energy source for the Button Shop. In 1880 the Button Shop burnt and was never rebuilt. Currently the Dam is being used for recreational and conservation purposes.

1.2.4 Description of the Dam and Appurtenances

The dam is earth-filled between stacked field-stone walls, with a cast-in-place concrete spillway about midway along the dam's length. The downstream face of the dam is near-vertical stacked stone with a few large trees growing at the toe and a noticeable bulge on the western portion of the stacked stone. The upstream face of the dam is sloped approximately 2 (horizontal) to 1 (vertical) and covered with stone facing. The abutments have large trees growing upon them.

The dam and spillway have a footpath crossing the crest, with a steel walkway across the spillway. The walkway consists of a steel beam (W36x135) laid on its side with wooden safety rails and steel posts. Steel angle irons brace the walkway beam in place against the spillway walls. The spillway has an inverted crane rail spanning the top of the spillway walls just behind the slots in the walls for the stop logs. Within the last eight to ten years the spillway was modified by adding an approximately three feet high, concrete sill within the spillway. Likewise, two small concrete walls have been added on the left side of the spillway to slow erosion that is ongoing behind the left wall of the spillway. Both vertical walls of the spillway have horizontal cracks about halfway up from the floor, which extend the full length of the spillway and completely through the spillway walls. There is significant deflection of the spillway walls toward the center of the spillway. The type and size of aggregate exposed in the crack and the lack of reinforcing steel appears to be consistent with concrete produced in the latter part of the 19th century.

The spillway is plugged with branches and mud. Although this mass of branches and mud appears similar to a beaver dam, close inspection suggests that it may be due to storm flows. In the past, the pond has been home to beavers; however, there is little fresh sign of beaver activity. A 15-inch diameter corrugated polyethylene pipe and screened inlet was installed from the pool in front of the dam extending slightly past the spillway, atop the concrete sill, to bypass the beaver dam. The pipe and inlet were installed within the last three years according to the limited records.

1.2.5 Operations and Maintenance

The Fyfeshire Pond is owned by The Conservation Commission of Bolton, MA, which is currently administered by Ms. Carol Gumbart. We understand that ongoing maintenance consists primarily of

maintaining the walking trail atop the dam, maintaining the hand rails crossing the channel spillway, and filling erosion features. Summer and winter operating procedures consists of periodic observation and filling of erosion features.

1.2.6 DCR Size Classification

Fyfeshire (Fish Pond) Dam has a maximum structural height of approximately 9 feet and a maximum storage capacity reported to be 46.2 acre-feet. Therefore, in accordance with Department of Conservation and Recreation Office of Dam Safety (DCR) classification, under Commonwealth of Massachusetts dam safety rules and regulations stated in 302 CMR 10.00 as amended by Chapter 330 of the Acts of 2002, Fyfeshire (Fish Pond) Dam is a small size structure.

1.2.7 DCR Hazard Classification

Fyfeshire (Fish Pond) Dam is located upstream of Lancaster Road in Berlin, MA. It appears that a failure of the dam at maximum pool will release between 23.8 and 46.2 acre-feet of water. Therefore, in accordance with Department of Conservation and Recreation classification procedures, under Commonwealth of Massachusetts dam safety rules and regulations stated in 302 CMR 10.00 as amended by Chapter 330 of the Acts of 2002, Fyfeshire (Fish Pond) Dam is classified as a significant hazard potential dam.

1.3 Pertinent Engineering Data

1.3.1 Drainage Area

The drainage area for Fyfeshire (Fish Pond) Dam is unknown and extends through the community of Bolton, Massachusetts. There are no records of the method used to determine drainage area of the dam which was constructed about 1878. There are several small ponds and wetlands shown on the USGS Quad Sheet upstream of the Fyfeshire (Fish Pond) Dam. The nature and characteristics of the watershed is unknown, but appears to be predominantly wooded, with some open farm/pasture and residential areas.

1.3.2 Reservoir

	Length (feet)	Width (feet)	Surface Area (acres)	Storage Volume (acre-feet)
Normal Pool				23.8*
Maximum Pool	N/A	N/A	N/A	46.2*
SDF Pool				

* From Jurisdictional Verification Form

1.3.3 Discharges at the Dam Site

There are no reported discharges or breaches from the Fyfeshire (Fish Pond) Dam, based on records and information provided by witnesses available at the time of inspection.

1.3.4 General Elevations (feet, measured from the bottom of the spillway)

A. Top of Dam	8.58 ft
B. Spillway Design Flood Pool	N/A
C. Normal Pool	N/A
D. Spillway Crest	3 ft
E. Upstream Water at Time of Inspection	~2.5 ft
F. Streambed at Toe of the Dam	0 ft
G. Low Point along Toe of the Dam	0 ft

1.3.5 Main Spillway

A. Type	Concrete
B. Length	9.67 ft
C. Invert Elevation	3 ft
D. Upstream Channel	debris filled
E. Downstream Channel	0 ft
F. Downstream Water	0 ft

1.3.6 Other Information

The Impoundment is managed as a conservation area and reportedly is home to the endangered Blanding's Turtle.

1.3.7 Design or As-built (Record)

The records pertaining to the Fyfeshire (Fish Pond) Dam were obtained from the Town of Bolton and the Massachusetts, Department of Conservation and Recreation (DCR). The United States Army Corp of Engineers was queried for records, but none were available. No construction records are available for this dam.

1.3.8 Operating Records

Operational records consist of a few letters regarding minor erosion repairs, funding documents, invoices, wildlife control (beavers), and other miscellaneous records. Bolton Conservation Commission maintains and updates the available records.

SECTION 2

2.0 INSPECTION

2.1 Visual Inspection

Fyfeshire (Fish Pond) Dam was inspected on July 17, 2008. At the time of the inspection, the weather was clear with a very slight breeze. Temperature was approximately 80 degrees. No significant amount of rainfall had fallen previous to the inspection date. Photographs to document the current conditions of the dam were taken during the inspection and are included in Appendix A. The level of the impoundment was approximately +2.5 feet, measured from the bottom of the spillway. Underwater areas were not inspected. A copy of the inspection checklist is included in Appendix B.

2.1.1 General Findings

In general, Fyfeshire (Fish Pond) Dam was found to be in unsafe condition with the spillway and downstream walls as the major concerns. The specific concerns are identified in more detail in the sections below:

2.1.2 Dam

The Fyfeshire (Fish Pond) Dam is approximately 88 feet long with a crest width of approximately 12 feet. Based on available information and visual observations, the dam is constructed of dry-stack stone walls at the upstream and downstream faces with earth fill between them and a concrete spillway in the approximate center. The left side of the spillway is located 39 feet from the left abutment.

2.1.2.1 Abutments

The abutments on both the left and right sides of the dam appear to be solid and dry. There is thick grass along the top of abutments and crest of the dam and only a few trees nearby on either side. At the corner of the right abutment, a tree has fallen over, removing the root ball and exposing a spherical volume within the pond embankment. This area doesn't appear to have weakened the dam abutment, but could be a cause for concern with erosion. See Photos 10 & 11.

2.1.2.2 Upstream Face

The upstream face of the dam consists of a battered (sloped) wall of smooth flat rocks. The rock face of the dam is in satisfactory condition with little observable erosion or wear. Trees are present on the right side face. See Photos 8 & 9. The pond appears stagnant and the pool directly in front of the dam is heavily silted in. Therefore, the visual inspection can only verify the condition of the face of the dam to the mud line. At the time of the inspection the mud line was completely visible and only partially submerged.

2.1.2.3 Crest

The crest of the dam is currently part of a walking path in the conservation area. Both sides of the path are grass-covered. The left side of the dam has juniper bushes planted on the upstream side of the crest. Evidence of significant erosion is found on the left side of the dam at the point where the spillway wall and the earth dam structure meet. The area was recently repaired with small 2-foot tall, cast-in-place concrete walls, retaining the soil within the walking path. The right side of the crest appears in better condition, with no sign of notable erosion, and only grass along the crest. See Photos 1 & 2.

2.1.2.4 *Downstream Face*

The downstream face of the dam is a vertical dry-stacked stone wall on both sides of the spillway. The left side of the wall is straight and has no noticeable batter. There is a large tree at the base of the wall; see Photos 25 & 26 in Appendix A. The right side of the downstream face is the same construction; however, it is bulged and leaning significantly along its length. See Photo 27 in Appendix A. The downstream face of the dam appears dry and shows no evidence of seepage.

2.1.2.5 *Drains*

There is no evidence and no record of any drains for the dam.

2.1.2.6 *Instrumentation*

The Fyfeshire Dam has no instrumentation of any kind.

2.1.2.7 *Access Roads and Gates*

The dam is accessed by the public through the gate at 500 Watoquadoc Hill Road in Fyfeshire Conservation Area in Bolton. Fyfeshire Dam can only currently be accessed by a foot path from the small pond near the entrance to the park. Another access point was observed during the inspection, southeast of the dam, through the private residence downstream of the dam. This access point has a gate across it.

2.1.3 Appurtenant Structures

2.1.3.1 *Primary Spillway*

The spillway for the Fyfeshire Dam is located approximately in the center of the dam and is a rectangular opening about 9.67 feet wide. The earthen dam structure is retained with vertical concrete walls on the left and right of the spillway. See Photo 17.

The spillway walls are made of concrete with aggregate sizes as large as approximately 6 inches in diameter. The concrete is consistent with the concrete produced in the late 19th century. The right (west) wall appears to be straight and vertical with a horizontal crack extending from upstream to downstream. The left (east) wall of the spillway has a large horizontal crack, which appears to penetrate completely through the thickness of the wall and extends from upstream to downstream. The left wall of the spillway appears to be bulged or folded such that the horizontal crack projects toward the center of the spillway many inches and the portion above and below the crack is leaning significantly (estimated 10 degrees) away from the center of the spillway. See Photos 18 through 25 in Appendix A for the spillway walls.

The foot path crosses the spillway with a steel foot bridge 5.58 feet above the spillway weir. The foot bridge is a W36x135 steel beam laid on its side for use as a walking surface across the spillway. Welded to the under side of the beam are steel sections of 2.5 inch angle, bracing the spillway walls.

A concrete sill, approximately 3-feet high, was added inside the spillway channel between 8 and 10 years ago (Photos 18, 22, & 31). The spillway is currently partially choked above the sill with branches, mud, and sticks. A 15-inch corrugated polyethylene pipe is protruding through the debris and over the sill within the spillway. The pipe appears to be connected to an inlet about 30 feet upstream of the dam. The inlet is covered with a large metal screen and was partially visible on the day of the inspection. Due to the low water level, water was not flowing through the pipe. This structure was reportedly installed to discourage beavers from damming the spillway. See Photos 18 and 30 thru 32 for the spillway pipe.

The spillway for the dam has an inverted crane rail spanning the top of the spillway walls just behind the slots in the walls for the stop logs.

2.1.3.2 *Low Level Outlets*

The only outlet is the main spillway shown in the photos. At the time of inspection, water was not flowing from the outlet pipe, or over the concrete weir.

2.1.3.3 *Auxiliary/Emergency Spillway*

An auxiliary spillway has not been constructed on the Fyfeshire (Fish Pond) Dam.

2.1.4 Downstream Area

The downstream area beyond the Fyfeshire (Fish Pond) Dam is a gully approximately 90 feet wide and 9 feet deep with moderately sloped embankment and stream in the middle. There is no trail below the dam; however, access is not difficult on foot. The area is generally wooded with trees and brush. Approximately 300 feet downstream and left of the dam, a relatively new residence is present. The home appears to be above the elevation of the dam. See Photos 33 and 34.

The downstream face of the dam is covered with thick brush on the right side of the spillway, and mostly clear on the left side, except for a large tree approximately two feet in diameter located next to the dam wall. The small stream bed is lined with rocks ranging from cobbles to 3-foot diameter boulders. At the time of inspection the stream bed had standing water but no discernable flow. Also at the time of inspection there was no evidence of seepage from the dam walls. See Photo 17.

Further downstream, there is a wetland and heavily wooded stream with thick underbrush. The nearest bridge is about $\pm 1,300$ feet downstream, and the Lancaster Road crossing is about $\pm 3,100$ feet downstream of the dam.

2.1.5 Reservoir Area

The reservoir is Fyfeshire Pond, also known as Fish Pond. It has a surface area estimated from the GIS figures (See Figure 2) to be 9 acres. The pond is visibly shallow as the bottom can be seen in more clear areas, and the majority of the pond is covered by lilies. Most of the pond is surrounded by low areas, with gradually sloping banks. However, in the immediate vicinity of the dam the banks are steeper. The pond is entirely surrounded by woods, primarily deciduous but with a few areas of mixed deciduous and evergreens. See Photos 13 thru 16 in Appendix A

The Fyfeshire Dam is located at the south east corner of the pond, facing south going downstream. The dam and screened inlet is located in a small cove in the corner of the pond, as shown in Figures 1 and 2, and on Photo 4 in Appendix A.

2.2 Caretaker Interview

The interview with the caretaker of the dam occurred on July 17, 2008. Ms. Carol Gumbart, the Conservation Administrator of the Town of Bolton Conservation Department, is considered the caretaker for the purposes of the Phase I Assessment. Ms. Gumbart has been the administrator for the Conservation Commission for 8 years and is familiar with the Fyfeshire Dam.

The dam is used only for conservation, recreation, and hiking. No regular maintenance is done unless a problem arises, and up until recently there were no regular removal or placement of stop logs to control

water level. In the last few years, beaver have begun blocking the spillway; therefore, the outlet pipe was installed to keep the water levels at the spillway level. However, there is little evidence of recent beaver activity.

At the time of the interview, the Conservation Commission did not have an emergency action plan in place. Also, the Conservation Commission has no written policy or manual regarding the operation and maintenance of the dam.

Ms. Rona Balco, a Bolton resident and active volunteer in the Fyfeshire Conservation Area, was also invited to the visit. Ms. Balco had been the organizer for the few repairs on the Fyfeshire (Fish Pond) Dam in 1997, and has continued trail maintenance in the area. Her knowledge of the area, past repairs and inspections, and history of William E. Fyfe was very helpful in the site visit.

2.3 Operation and Maintenance Procedures

2.3.1 Operational Procedures

Since the Fyfeshire Conservation Area is used for recreation use only and the pond use is restricted to conservation, there is no scheduled operation of the facility.

2.3.2 Maintenance of Dam and Operating Facilities

Maintenance of the dam consists of leak repair, trail maintenance and erosion control. These have been done on an as-needed basis. The projects have been completed by volunteers and funded by the Conservation Commission. Some records have been kept for each improvement and inspection.

2.4 Emergency Warning System

No Emergency Warning System or Emergency Action Plan was available at the time of inspection for the Fyfeshire Dam.

2.5 Hydrologic/Hydraulic Data

No hydrologic and hydraulic analysis was available at the time of inspection for the Fyfeshire Dam.

2.6 Structural Stability/Overtopping Potential

2.6.1 Structural Stability

The structural stability of the Fyfeshire Dam appears to be in unsafe condition based upon the visual inspection. In particular, the downstream face on the right side and the cracked and broken left wall of the spillway contribute to the "Unsafe" designation. These two walls appear to be of concern and could have significant impacts to the entire structure if they fail.

No structural stability analysis of the Fyfeshire (Fish Pond) Dam was available at the time of inspection.

2.6.2 Overtopping Potential

No overtopping data or analysis for the Fyfeshire (Fish Pond) Dam was available at the time of the inspection..

SECTION 3

3.0 ASSESSMENTS AND RECOMMENDATIONS

3.1 Assessments

In general, the overall condition of Fish Pond Dam is Unsafe. The dam was found to have structural deficiencies in the embankments due to wall instability, large tree growth, and failing concrete spillway.

The following recommendations and remedial measures generally describe the recommended approach to address current deficiencies at the dam. Prior to undertaking recommended maintenance, repairs and remedial measure, the applicability of environmental permits needs to be determined prior to undertaking activities that may occur within resource areas under the jurisdiction of local conservation commissions, MADEP, or other regulatory agencies.

3.2 Studies and Analyses

We understand that the Bolton Conservation Commission desires to keep the Fyfeshire Dam and pond in operation for environmental and conservation purposes. To bring the dam up to a minimum safe condition, we recommend that the following studies should be completed to evaluate concerns and/or comply with current regulations:

- A. Hydraulic & Hydrologic analyses;
- B. Stability Analysis;
- C. Seepage Evaluation.
- D. Downstream Hazard Assessment

The facility should also have the following documents prepared so that future modifications and repairs can be made with dam safety in mind.

- E. Operations and Maintenance (O & M) Manual;
- F. Emergency Action Plan (EAP).

3.3 Yearly Recommendations

At a minimum, the spillway should be checked for accumulated debris, wood, mud, etc., and cleaned as needed. That should be done at least quarterly (every three months) and after every significant storm event. Other recommendations will require further study.

3.4 Recommendations, Maintenance, and Minor Repairs

Such recommendations will require further study.

3.5 Remedial Measures

Due to the unsafe condition of the dam, the dam will require significant remedial action. Such measures could include reconstruction, replacement, or breaching.

3.6 Alternatives

An alternative could include constructing a downstream buttress along with replacing the spillway.


3.7 Opinion of Probable Construction Costs

Our opinion of the Probable Cost for implementing the recommendations and alternatives include:

A. Engineering and Permitting	\$75,000 to \$125,000
B. Operation and Maintenance Manual	\$8,000 to \$16,000
C. Emergency Action Plan	\$8,000 to \$16,000
D. 1. Construction	\$150,000 to \$250,000
2. Dam Breaching	\$15,000 to \$50,000
E. Annual Maintenance & Inspection	\$8,000 to \$16,000

This information is based upon published estimating guides, current market pricing, and manufacturer information where applicable and our opinion regarding the necessary remediation of the dam.

FIGURES



NOTES:

1. CIRCLES INDICATE 500-FOOT AND 1/2-MILE RADII.
2. BASED ON USGS TOPOGRAPHIC QUADRANGLE MAPS FOR CLINTON AND HUDSON, MASSACHUSETTS, REVISED 1988.

AMEC Earth & Environmental

2 ROBBINS ROAD
WESTFORD, MASSACHUSETTS 01886



CLIENT LOGO

CLIENT

FISH POND DAM

NATIONAL I.D. NO.

MA01512

DWN BY:

R. BOWMAN

DATUM:

N/A

DATE:

12 JUNE 2008

TITLE

SITE LOCUS

CHK'D BY:

J. HOYT

REV. NO.:

A

PROJECT NO:

X-XXXX-XXXX

PROJECTION:

N/A


SCALE:


AS SHOWN

FIGURE No.

1

**FYFESHIRE DAM (A.K.A. FISH POND DAM)
BOLTON, MASSACHUSETTS**



CLIENT LOGO	CLIENT	DWN BY: R. BOWMAN		FYFESHIRE DAM (A.K.A. FISH POND DAM) NATIONAL I.D. NO. MA01512 BOLTON, MASSACHUSETTS	REV. NO.: A
	AMEC Earth & Environmental 2 ROBBINS ROAD WESTFORD, MASSACHUSETTS 01886		CHK'D BY: J. HOYT		DATE: 12 JUNE 2008
TITLE			PROJECT NO: 7-7699-0000		
PROJECTION: N/A			FIGURE No. 2		
SCALE: AS SHOWN					
AERIAL SITE PLAN					



APPENDIX A
PHOTOGRAPHS



Photo #1: Taken from the left abutment (east facing west) facing dam, and cove upstream




Photo #2: Taken from left abutment (east facing west) of dam and downstream.



Photo #3 Upstream face of dam taken at left abutment (east facing west)



Photo #4: Screened inlet for spillway outlet pipe.



Photo #5: Upstream face, spillway and footbridge taken from right embankment.



Photo #6: Debris dam and sedimentation in upstream pool.



Photo #7: Debris dam and sedimentation in upstream pool.



Photo #8: Trees in upstream face (right side)



Photo #9: Trees in upstream face (right side)



Photo #10: Fallen tree upstream of the right side of abutment (view south).



Photo #11: Fallen tree upstream of the right side of abutment (view west).



Photo #12: Right side upsteraam face, abutment and cove embankment



Photo #13: Fyfeshire Pond upstream of the dam, within the cove (view north)



Photo #14: Fyfeshire Pond upstream of the dam, within the cove (view NNE)



Photo #15: Fyfeshire lower Pond (Fish Pond) upstream of cove with dam.



Photo #16: Fyfeshire Pond to the right of the cove with the dam.



Photo #17: Downstream of spillway



Photo #18: Downstream of spillway facing the right (west) spillway wall and dam wall



Photo #19: Downstream of spillway facing the right (west) spillway wall and dam wall with grape vine



Photo #20: Major crack in left spillway wall and steel bracing



Photo #21: Deterioration of left, downstream spillway wall



Photo #22: Left side of spillway.



Photo #23: Major crack in the left spillwaywall downstream



Photo #24: Major crack in the left spillwaywall downstream



Photo #25: Major crack in left spillway wall ,upstream



Photo #26: Downstream face, left side



Photo #27: Downstream face, right side



Photo #28: Downstream face left side.



Photo #29: Repair section on left side of spillway



Photo #30: Debris dam at the spillway and pipe outlet.



Photo #31: Debris dam at the spillway and pipe outlet.



Photo #32: Evidence of old beaver activity



Photo #33: Stream Downstream facing south, closest residence in background



Photo #34: Residence downstream from Fyfeshire Dam.

APPENDIX B
INSPECTION CHECKLIST

Dam Evaluation Summary Detail Sheet

1. NID ID: MA01512	2. Dam Name: Fish Pond Dam (AKA Fyfeshire Dam)	3. Dam Location: Bolton, MA
4. Inspection Date: 7/17/2008	5. Last Insp. Date: unknown	6. Next Inspection: 7/16/2013
7. Inspector: D. E. Tate	8. Consultant: AMEC Earth & Environmental, Inc.	
9. Hazard Code: Significant (Class 2)	10. Insp. Frequency: Significant-5 Yrs.	11. Insp. Condition: Unsafe
E1. Design Methodology:	1	E7. Low-Level Discharge Capacity: 1
E2. Level of Maintenance:	2	E8. Low-Level Outlet Physical Condition: 1
E3. Emergency Action Plan:	2	E9. Spillway Design Flood Capacity:
E4. Embankment Seepage:	3	E10. Overall Physical Condition of the Dam: 1
E5. Embankment Condition:	2	E11. Estimated Repair Cost (in thousand \$):
E6. Concrete Condition:	1	

Evaluation Description

E1: DESIGN METHODOLOGY

1. Unknown Design – no design records available
3. Some standard design features
5. State of the art design – design records available

E2: LEVEL OF MAINTENANCE

1. No evidence of maintenance, no O&M manual
2. Very little maintenance, no O&M manual
3. Some level of maintenance and standard procedures
4. Adequate level of maintenance and standard procedures
5. Detailed maintenance plan that is executed

E3: EMERGENCY ACTION PLAN

1. No plan or idea of what to do in the event of an emergency
2. Some idea but no written plan
3. No formal plan but well thought out
4. Available written plan that needs updating
5. Detailed, updated written plan available and filed with MADCR

E4: EMBANKMENT SEEPAGE

1. Severe piping and/or seepage with no monitoring
2. Evidence of monitored piping and seepage
3. No piping but uncontrolled seepage
4. Controlled seepage
5. No seepage or piping

E5: EMBANKMENT CONDITION

1. Severe erosion and/or large trees
2. Significant erosion or significant woody vegetation
3. Brush and exposed embankment soils, or moderate erosion
4. Unmaintained grass, rodent activity and maintainable erosion
5. Well maintained healthy uniform grass cover

E6: CONCRETE CONDITION

1. Major cracks, misalignment, discontinuities causing leaks, seepage or stability concerns
2. Cracks with misalignment inclusive of transverse cracks with no misalignment
3. Significant longitudinal cracking and minor transverse cracking
4. Spalling and minor surface cracking
5. No apparent deficiencies

E7: LOW LEVEL OUTLET DISCHARGE CAPACITY

1. No low level outlet
2. Outlet with insufficient drawdown capacity
3. Inoperable gate with potentially sufficient drawdown capacity
4. Operable gate with sufficient drawdown capacity
5. Operable gate with capacity greater than necessary

E8: LOW LEVEL OUTLET PHYSICAL CONDITION

1. Outlet inoperative needs replacement, non-existent or inaccessible
2. Outlet inoperative needs repair
3. Outlet operable but needs repair
4. Outlet operable but needs maintenance
5. Outlet and operator operable and well maintained

E9: SPILLWAY DESIGN FLOOD CAPACITY

1. 0 - 20% of the SDF
2. 21- 40% of the SDF
3. 41- 60% of the SDF
4. 61- 80% of the SDF
5. 81- 100% of the SDF

E10: OVERALL PHYSICAL CONDITION OF THE DAM

1. *UNSAFE* – Major structural, operational, and maintenance deficiencies exist under normal operating conditions
2. *POOR* - Significant structural, operation and maintenance deficiencies are clearly recognized under normal loading conditions
3. *FAIR* - Significant operational and maintenance deficiencies, no structural deficiencies. Potential deficiencies exist under unusual loading conditions that may realistically occur. Can be used when uncertainties exist as to critical parameters
4. *SATISFACTORY* - Minor operational and maintenance deficiencies. Infrequent hydrologic events would probably result in deficiencies.
5. *GOOD* - No existing or potential deficiencies recognized. Safe performance is expected under all loading including SDF

E11: ESTIMATED REPAIR COST

Estimation of the total cost to address all identified structural, operational, maintenance deficiencies. Cost shall be developed utilizing standard estimating guides and procedures

Changes/Deviations to Database Information since last inspection

No previous inspection was available. Town records show that the spillway was inspected by an engineer (GOLDSMITH, PREST & RINGWALL, INC.) in January, 1998, who recommended its replacement. E9 Spillway Capacity - the capacity of the spillway relative to the design storm is unknown.

DAM SAFETY INSPECTION CHECKLIST

NAME OF DAM:	Fish Pond Dam	STATE ID #:	3-14-34-2
REGISTERED:	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	NID ID #:	MA01512
STATE SIZE CLASSIFICATION:	Small	STATE HAZARD CLASSIFICATION:	Significant
<u>LOCATION INFORMATION</u>			
CITY/TOWN:	Bolton	COUNTY:	Worcester
DAM LOCATION:	Wattuquodoc Hill Road, Bolton MA		
USGS QUAD:	Clinton and Hudson ?	LAT.:	42.14182
DRAINAGE BASIN:		LONG.:	-72.08502
IMPOUNDMENT NAME(S):	Fish Pond	RIVER:	Fish Pond
<u>GENERAL DAM INFORMATION</u>			
TYPE OF DAM:	REPG	OVERALL LENGTH (FT):	?
PURPOSE OF DAM:	Recreational	NORMAL POOL STORAGE (ACRE-FT):	23.8
YEAR BUILT:	1940	MAXIMUM POOL STORAGE (ACRE-FT):	46.2
STRUCTURAL HEIGHT (FT):	9	EL. NORMAL POOL (FT):	?
HYDRAULIC HEIGHT (FT):	5.1	EL. MAXIMUM POOL (FT):	?
<u>FOR INTERNAL MADCR USE ONLY</u>			
FOLLOW-UP INSPECTION REQUIRED:	<input type="checkbox"/> YES <input type="checkbox"/> NO	CONDITIONAL LETTER:	<input type="checkbox"/> YES <input type="checkbox"/> NO

NAME OF DAM: <u>Fish Pond Dam</u>		STATE ID #: <u>3-14-34-2</u>
		NID ID #: <u>MA01512</u>
<u>INSPECTION SUMMARY</u>		
DATE OF INSPECTION: <u>7.17.08</u>	DATE OF PREVIOUS INSPECTION: <u>UNKNOWN</u>	
TEMPERATURE/WEATHER: <u>80° CLEAR</u>	ARMY CORP PHASE I: <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO If YES, date _____	
CONSULTANT: <u>AMEC</u>	PREVIOUS DCR PHASE I: <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO If YES, date _____	
BENCHMARK/DATUM: _____		
OVERALL CONDITION: <input type="checkbox"/> <u> </u> <input checked="" type="checkbox"/> <u> </u>	DATE OF LAST REHABILITATION: <u>UNKNOWN</u>	<u>1970?</u>
EL. TAIL WATER DURING INSP.: _____		
<u>PERSONS PRESENT AT INSPECTION</u>		
NAME	TITLE/POSITION	REPRESENTING
<u>Rona</u>	<u>Volunteer</u>	<u>Bolton Fred Com</u>
<u>Carol</u>	<u>Administrator</u>	<u>Bolton Fred Com</u>
<u>Harb</u>	<u>Engineer</u>	<u>AMEC</u>
<u>Lao</u>	<u>Engineer</u>	<u>"</u>
<u>Doug</u>	<u>Engineer</u>	<u>"</u>
<u>EVALUATION INFORMATION</u>		
E1) TYPE OF DESIGN	<input type="checkbox"/> <u> </u> <input checked="" type="checkbox"/> <u> </u>	<input type="checkbox"/> <u> </u> <input checked="" type="checkbox"/> <u> </u>
E2) LEVEL OF MAINTENANCE	<input type="checkbox"/> <u> </u> <input checked="" type="checkbox"/> <u> </u>	<input type="checkbox"/> <u> </u> <input checked="" type="checkbox"/> <u> </u>
E3) EMERGENCY ACTION PLAN	<input type="checkbox"/> <u> </u> <input checked="" type="checkbox"/> <u> </u>	<input type="checkbox"/> <u> </u> <input checked="" type="checkbox"/> <u> </u>
E4) EMBANKMENT SEEPAGE	<input type="checkbox"/> <u> </u> <input checked="" type="checkbox"/> <u> </u>	<input type="checkbox"/> <u> </u> <input checked="" type="checkbox"/> <u> </u>
E5) EMBANKMENT CONDITION	<input type="checkbox"/> <u> </u> <input checked="" type="checkbox"/> <u> </u>	<input type="checkbox"/> YES <input type="checkbox"/> NO
E6) CONCRETE CONDITION	<input type="checkbox"/> <u> </u> <input checked="" type="checkbox"/> <u> </u>	<input type="checkbox"/> YES <input type="checkbox"/> NO
E7) LOW-LEVEL OUTLET CAP	<input type="checkbox"/> <u> </u> <input checked="" type="checkbox"/> <u> </u>	<input type="checkbox"/> YES <input type="checkbox"/> NO
E8) LOW-LEVEL OUTLET COND.	<input type="checkbox"/> <u> </u> <input checked="" type="checkbox"/> <u> </u>	<input type="checkbox"/> YES <input type="checkbox"/> NO
E9) SPILLWAY DESIGN FLOOD	<input type="checkbox"/> <u> </u> <input checked="" type="checkbox"/> <u> </u>	<input type="checkbox"/> YES <input type="checkbox"/> NO
E10) GENERAL CONDITIONS	<input type="checkbox"/> <u> </u> <input checked="" type="checkbox"/> <u> </u>	<input type="checkbox"/> YES <input type="checkbox"/> NO
E11) ESTIMATED REPAIR COST (\$000)		
ROADWAY OVER CREST <input type="checkbox"/> YES <input type="checkbox"/> NO		
BRIDGE NEAR DAM <input type="checkbox"/> YES <input type="checkbox"/> NO		
SIGNATURE OF INSPECTING ENGINEER: _____		

NAME OF DAM: Fish Pond Dam		STATE ID #: 3-14-34-2									
		NID ID #: MA01512									
<table border="0"> <tr> <td colspan="2"> OWNER: ORGANIZATION NAME/TITLE STREET TOWN, STATE, ZIP PHONE FAX EMAIL OWNER TYPE </td> <td colspan="2"> Town of Bolton Conservation Commission Town Hall 663 Main Street Bolton MA, 01740 978-779-3304 </td> </tr> <tr> <td colspan="2"> CARETAKER: ORGANIZATION NAME/TITLE STREET TOWN, STATE, ZIP PHONE FAX EMAIL </td> <td colspan="2"> Town of Bolton Bolton MA 01740 508-877-2297 </td> </tr> </table>				OWNER: ORGANIZATION NAME/TITLE STREET TOWN, STATE, ZIP PHONE FAX EMAIL OWNER TYPE		Town of Bolton Conservation Commission Town Hall 663 Main Street Bolton MA, 01740 978-779-3304 		CARETAKER: ORGANIZATION NAME/TITLE STREET TOWN, STATE, ZIP PHONE FAX EMAIL		Town of Bolton Bolton MA 01740 508-877-2297 	
OWNER: ORGANIZATION NAME/TITLE STREET TOWN, STATE, ZIP PHONE FAX EMAIL OWNER TYPE		Town of Bolton Conservation Commission Town Hall 663 Main Street Bolton MA, 01740 978-779-3304 									
CARETAKER: ORGANIZATION NAME/TITLE STREET TOWN, STATE, ZIP PHONE FAX EMAIL		Town of Bolton Bolton MA 01740 508-877-2297 									
PRIMARY SPILLWAY TYPE <u>Open Channel Concrete</u>											
SPILLWAY LENGTH (FT)		<u>N/A</u>									
AUXILIARY SPILLWAY TYPE		<u>N/A</u>									
NUMBER OF OUTLETS		<u>1</u>									
TYPE OF OUTLETS		<u>Spillway</u>									
DRAINAGE AREA (SQ MI)		<u>N/A</u>									
HAS DAM BEEN BREACHED OR OVERTOPPED		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO IF YES, PROVIDE DATE(S)									
FISH LADDER (LIST TYPE IF PRESENT) <u>None</u>											
DOES CREST SUPPORT PUBLIC ROAD?		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO IF YES, ROAD NAME:									
PUBLIC BRIDGE WITHIN 50' OF DAM?		<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO IF YES, ROAD/BRIDGE NAME: <u>Pedestrian Foot Bridge</u>									

Embankment Crest

NAME OF DAM: <u>Fish Pond Dam</u>		STATE ID #: <u>3-14-34-2</u>	
INSPECTION DATE: <u>7/17/2008</u>		NID ID #: <u>MA01512</u>	
EMBANKMENT			
AREA INSPECTED	CONDITION	OBSERVATIONS	NO ACTION MONITOR REPAIR
CREST	SURFACE TYPE	Soil	
	SURFACE CRACKING	None	
	SINKHOLES, ANIMAL BURROWS	Sinkhole / Erosion	
	VERTICAL ALIGNMENT (DEPRESSIONS)	Depression	
	HORIZONTAL ALIGNMENT	OK	
	RUTS AND/OR PUDDLES	Yes	
	VEGETATION (PRESENCE/CONDITION)	Grass, Juniper, briars, Poison Ivy / Wood & Non-Wood Shrubs	
	ABUTMENT CONTACT	OK - few trees	
ADDITIONAL COMMENTS:			

Downstream Side

NAME OF DAM: Fish Pond Dam		STATE ID #: 3-14-34-2	
INSPECTION DATE: 7		NID ID #: MA01512	
EMBANKMENT			
AREA INSPECTED	CONDITION	OBSERVATIONS	NO ACTION MONITOR REPAIR
D/S SLOPE	WET AREAS (NO FLOW) SEEPAGE SLIDE, SLOUGH, SCARP EMB.-ABUTMENT CONTACT SINKHOLE/ANIMAL BURROWS EROSION UNUSUAL MOVEMENT VEGETATION (PRESENCE/CONDITION)	No seeping	
		No seepage	
		West Embankment Bulging	
		Soil's Factory	
		None	
		East Embankment, with repair walls	
		Bulging on West	
		Woody & Non Woody Shrubs	
ADDITIONAL COMMENTS:			

Upstream side

NAME OF DAM: Fish Pond Dam		STATE ID #: 3-14-34-2	
INSPECTION DATE:		MA01512	
EMBANKMENT			
AREA INSPECTED	CONDITION	OBSERVATIONS	NO ACTION MONITOR REPAIR
U/S SLOPE	SLIDE, SLOUGH, SCARP	None	
	SLOPE PROTECTION TYPE AND COND.	Slope w/ Rock Face Slope is 2:1	
	SINKHOLE/ANIMAL BURROWS	East Em. Animal burrow	
	EMB.-ABUTMENT CONTACT	Satisfactory	
	EROSION	East Embankment @ bridge	
	UNUSUAL MOVEMENT	None	
	VEGETATION (PRESENCE/CONDITION)	Woody & Non Woody Shrubs	
ADDITIONAL COMMENTS:			

Instrumentation

NAME OF DAM: Fish Pond Dam		STATE ID #: 3-14-34-2	
INSPECTION DATE:		NID ID #: MA01512	
EMBANKMENT			
AREA INSPECTED	CONDITION	OBSERVATIONS	NO ACTION MONITOR REPAIR
INSTR.	PIEZOMETERS	N/A	
	OBSERVATION WELLS	N/A	
	STAFF GAGE AND RECORDER	N/A	
	WEIRS	N/A	
	INCLINOMETERS	N/A	
	SURVEY MONUMENTS	N/A	
	DRAINS	N/A	
	FREQUENCY OF READINGS	N/A	
	LOCATION OF READINGS	N/A	
ADDITIONAL COMMENTS:			

Masonry Walls

NAME OF DAM: Fish Pond Dam		STATE ID #: 3-14-34-2	
INSPECTION DATE: _____		NID ID #: MA01512	
UPSTREAM AND/OR DOWNSTREAM MASONRY WALLS			
AREA INSPECTED	CONDITION	OBSERVATIONS	NO ACTION MONITOR REPAIR
D/S WALLS	WALL TYPE	Concrete Spilling (East)	
	WALL ALIGNMENT	Perpendicular to dam, midway	
	WALL CONDITION	Good (East)	
	HEIGHT: TOP OF WALL TO MUDLINE	min: max: avg:	
	SEEPAGE OR LEAKAGE	None	
	ABUTMENT CONTACT	None	
	EROSION/SINKHOLES BEHIND WALL	Along crest of East Embankment, behind wall	
	ANIMAL BURROWS	None	
	UNUSUAL MOVEMENT	East Wall cracked, leaning	
	WET AREAS AT TOE OF WALL	Spilling	
ADDITIONAL COMMENTS:			

Downstream Area

NAME OF DAM: <u>Fish Pond Dam</u>		STAE ID #: <u>3-14-34-2</u>	
INSPECTION DATE: _____		NID ID #: <u>MA01512</u>	
DOWNSTREAM AREA			
AREA INSPECTED	CONDITION	OBSERVATIONS	NO ACTION MONITOR REPAIR
D/S AREA	ABUTMENT LEAKAGE	<i>None</i>	
	FOUNDATION SEEPAGE	<i>None</i>	
	SLIDE,SLOUGH,SCARP	<i>West Ement's point</i>	
	WEIRS	<i>N/A</i>	
	DRAINAGE SYSTEM		
	INSTRUMENTATION		
	VEGETATION		
	ACCESSIBILITY		
	DOWNSTREAM HAZARD DESCRIPTION		
	DATE OF LAST EAP UPDATE		
ADDITIONAL COMMENTS:			


Misc.

NAME OF DAM: <u>Fish Pond Dam</u>		STATE ID #: <u>3-14-34-2</u>
INSPECTION DATE: _____		NID ID #: <u>MA01512</u>
MISCELLANEOUS		
AREA INSPECTED	CONDITION	OBSERVATIONS
MISC.	RESERVOIR DEPTH (AVG)	<u>Unknown Reported 1'-3'</u>
	RESERVOIR SHORELINE	<u>Wooded</u>
	RESERVOIR SLOPES	<u>Flats</u>
	ACCESS ROADS	<u>Foot Path</u>
	SECURITY DEVICES	<u>N/A</u>
	VANDALISM OR TRESPASS	YES: <input checked="" type="checkbox"/> NO: <input type="checkbox"/> WHAT: _____
	AVAILABILITY OF PLANS	YES: <input type="checkbox"/> NO: <input checked="" type="checkbox"/> DATE: _____
	AVAILABILITY OF DESIGN CALCS	YES: <input type="checkbox"/> NO: <input checked="" type="checkbox"/> DATE: _____
	AVAILABILITY OF EAP/LAST UPDATE	YES: <input type="checkbox"/> NO: <input checked="" type="checkbox"/> DATE: _____
	AVAILABILITY OF O&M MANUAL	YES: <input type="checkbox"/> NO: <input checked="" type="checkbox"/> DATE: <u>7/17/2008</u>
CARETAKER/OWNER AVAILABLE	YES: <input checked="" type="checkbox"/> NO: <input type="checkbox"/> PURPOSE: _____	
CONFINED SPACE ENTRY REQUIRED	YES: <input type="checkbox"/> NO: <input checked="" type="checkbox"/>	
ADDITIONAL COMMENTS: _____		

Primary Spillway

NAME OF DAM: Fish Pond Dam		STATE ID #: 3-14-34-2	
INSPECTION DATE:		MA01512	
PRIMARY SPILLWAY			
AREA INSPECTED	CONDITION	OBSERVATIONS	NO ACTION MONITOR REPAIR
SPILLWAY	SPILLWAY TYPE	Open channel concrete	
	WEIR TYPE	Concrete	
	SPILLWAY CONDITION	Poor	
	TRAINING WALLS	N/A	
	SPILLWAY CONTROLS AND CONDITION	15" PP to allow flow through beam dam	
	UNUSUAL MOVEMENT	Spilling with in poor condition See comment	
	APPROACH AREA	Beam Dam Debris	
	DISCHARGE AREA	Beam Dam Debris	
	DEBRIS	Beam Dam / Spill pipe	
	WATER LEVEL AT TIME OF INSPECTION		
ADDITIONAL COMMENTS:			
15" ID Polyethylene Pipe			
East Spilling wall is cracked & broken completely through			

Auxiliary Spillway

NAME OF DAM: <u>Fish Pond Dam</u>		STATE ID #: <u>3-14-34-2</u>	
INSPECTION DATE: _____		NID ID #: <u>MA01512</u>	
AUXILIARY SPILLWAY			
AREA INSPECTED	CONDITION	OBSERVATIONS	NO ACTION MONITOR REPAIR
SPILLWAY	SPILLWAY TYPE		
	WEIR TYPE		
	SPILLWAY CONDITION		
	TRAINING WALLS		
	SPILLWAY CONTROLS AND CONDITION		
	UNUSUAL MOVEMENT		
	APPROACH AREA		
	DISCHARGE AREA		
	DEBRIS		
	WATER LEVEL AT TIME OF INSPECTION		
ADDITIONAL COMMENTS:			

Outlet Works

NAME OF DAM: <u>Fish Pond Dam</u>		STATE ID #: <u>3-14-34-2</u>	
INSPECTION DATE: _____		NID ID #: <u>MA01512</u>	
OUTLET WORKS			
AREA INSPECTED	CONDITION	OBSERVATIONS	NO ACTION MONITOR REPAIR
OUTLET WORKS	TYPE	<u>A N/A</u>	
	INTAKE STRUCTURE		
	TRASHRACK		
	PRIMARY CLOSURE		
	SECONDARY CLOSURE		
	CONDUIT		
	OUTLET STRUCTURE/HEADWALL		
	EROSION ALONG TOE OF DAM	<u>None</u>	
	SEEPAGE/LEAKAGE	<u>None</u>	
	DEBRIS/BLOCKAGE	<u>Beaver Dam</u>	
UNUSUAL MOVEMENT			
DOWNSTREAM AREA	<u>Small stream / Rocks</u>		
MISCELLANEOUS			
ADDITIONAL COMMENTS:			

Concrete/Masonry Dams

NAME OF DAM: <u>Fish Pond Dam</u>		STATE ID #: <u>3-14-34-2</u>	
INSPECTION DATE: _____		NID ID #: <u>MA01512</u>	
CONCRETE/MASONRY DAMS			
AREA INSPECTED	CONDITION	OBSERVATIONS	NO ACTION MONITOR REPAIR
GENERAL	TYPE	N/A	
	AVAILABILITY OF PLANS		
	AVAILABILITY OF DESIGN CALCS		
	PIEZOMETERS		
	OBSERVATION WELLS		
	INCLINOMETERS		
	SEEPAGE GALLERY		
	UNUSUAL MOVEMENT		
	ADDITIONAL COMMENTS:		

Upstream Face

NAME OF DAM: Fish Pond Dam		STATE ID #: 3-14-34-2	
INSPECTION DATE:		MA01512	
CONCRETE/MASONRY DAMS			
AREA INSPECTED	CONDITION	OBSERVATIONS	NO ACTION MONITOR REPAIR
U/S FACE	TYPE SURFACE CONDITIONS CONDITIONS OF JOINTS UNUSUAL MOVEMENT ABUTMENT CONTACTS	N/A	
		ADDITIONAL COMMENTS:	

NAME OF DAM: Fish Pond Dam		STATE ID #: 3-14-34-2	
INSPECTION DATE:		NID ID #: MA01512	
CONCRETE/MASONRY DAMS			
AREA INSPECTED	CONDITION	OBSERVATIONS	NO ACTION MONITOR REPAIR
D/S FACE	TYPE SURFACE CONDITIONS CONDITIONS OF JOINTS UNUSUAL MOVEMENT ABUTMENT CONTACTS DRAINS LEAKAGE	N/A	
		ADDITIONAL COMMENTS:	

Concrete Crest

NAME OF DAM: <u>Fish Pond Dam</u>		STATE ID #: <u>3-14-34-2</u>
INSPECTION DATE: _____		NID ID #: <u>MA01512</u>
CONCRETE/MASONRY DAMS		
AREA INSPECTED	CONDITION	OBSERVATIONS
CREST	TYPE SURFACE CONDITIONS CONDITIONS OF JOINTS UNUSUAL MOVEMENT HORIZONTAL ALIGNMENT VERTICAL ALIGNMENT	N/A
		ADDITIONAL COMMENTS:

APPENDIX C
PREVIOUS REPORTS AND REFERENCES

PREVIOUS REPORTS AND REFERENCES

The following is a list of reports that were located during the file review, or were referenced in previous reports.

Jurisdictional and Ownership Inspections, Tighe and Bond Engineers, Project #: P07-2441-X05, July 18, 2007

M-0440-4-50

7/18/2007

William C. Salomaa, Program Manager
Department of Conservation and Recreation
Office of Dam Safety
John Augustus Hall
180 Beaman Street
West Boylston, MA 01583

*JURISDICTION
AT CLASS II*
2/08
P

Re: Jurisdictional and Ownership Inspections
Project #P07-2441-X05
Nat. ID# MA01512
Dam Name: Fish Pond Dam
Town/City: Bolton

Dear Mr. Salomaa:

In accordance with the scope of engineering services for the Jurisdictional and Ownership Inspection Project, we are submitting to you herewith the following listed items for the above referenced dam:

1. Jurisdiction Verification Form.
2. Overview photos of dam.
3. Not to scale sketch of dam.
4. Locus map of dam.

We appreciate the opportunity to provide DCR with our engineering services. Should you have any questions, please contact the undersigned at 413-572-3235.

Very truly yours,

TIGHE & BOND, INC.

David M. Lenart
David M. Lenart, P.E.
Associate

Commonwealth of Massachusetts
Department of Conservation and Recreation (DCR)
Office of Dam Safety (ODS)

For Office of Dam Safety Records - Jurisdiction Verification Form

Consultant Firm Name: Tighe&Bond, Inc.

Consultant Staff: B. Raymond

Date: 6/28/2007

Town: Bolton

Name of dam: Fish Pond Dam

National Dam ID Number: MA01512

State ID Number: 3-14-34-2

Structural Height of Dam: (measured vertical height of dam
as measured from streambed at downstream
toe to crest of dam)

9 feet

Maximum Size of Impoundment: (estimated volume in acre
feet of pool at top of dam elevation).....

46.2 acre-feet

Hydraulic Height of Dam: (measured vertical height of normal
pool impoundment from streambed at downstream toe to
Spillway Crest.....

5.1 feet

Normal Pool Size of Impoundment: (estimated volume in acre
feet of pool at spillway crest elevation).....

23.8 acre-feet

Dam Location Lat. 42.41530

Long. -71.64902

Public Road On Crest: No If Public Road, is there a Bridge Across the Spillway? No

Consultant Recommendation:

Does the dam meet the definition of a jurisdictional dam in accordance with MGL Chapter 253 Section 44 - 48 and
302 CMR 10.00 Dam Safety Regulations? X Yes ___ No Is the dam currently Jurisdictional? No

Suggested Hazard Potential Class: ___ High X Significant ___ Low Existing Hazard Potential Class: Low

Check here if this statement applies: √ The Suggested Hazard Potential Class is based upon a cursory review of the
limited information available during this assignment. The suggested class is not intended to be an actual recommended
classification of the structure. Additional study may be necessary to establish the record Hazard Potential Class.
ODS will make the final determination.

Additional Comments: Significant Downstream Hazard - Failure of dam would likely result in damage to Collins
Road (approximately 1200 feet downstream) and low lying homes along Lancaster Road.

Consultant Signature: David H. Lewis

Title: Associate

7/18/2007

Date

For Office of Dam Safety Use

Name of ODS Staff Reviewing Recommendations: [Signature] Date: 7/10/08

Office Staff Review Concludes: (mark with X)

The Dam X Does ___ Does Not Meet the Definition of a Jurisdictional Dam.


Data contained on this form was entered into the Office of Dam Safety Database on 7/10/08

Site Sketch:

Nat ID#: MA01512


Tighe & Bond
Consulting Engineers
Environmental Specialists

JOB NO. M440-4-50 SHEET _____ OF _____
CLIENT BOLTON, MA
SUBJECT MA01512 Fish Pond Dam
PREPARED BY BJR DATE 6/28/07 CHECKED BY _____ DATE _____




Site Photo: 1

NatID: MA01512




Site Photo: 2





BASED ON USGS TOPOGRAPHIC MAP FOR
CLINTON & HUDSON
MASSACHUSETTS QUADRANGLES
REVISED 1988
3-METER CONTOUR INTERVAL



SITE LOCUS

FISH POND DAM
BOLTON, MASSACHUSETTS
MA01512

Tighe&Bond

JULY 2007

V:\Projects\MM0440\MA01512\usgs.mxd

Department of Conservation and Recreation DAM Detail

National ID: MA01512
Dam Location: Bolton
Dam Name: Fish Pond Dam
AKA Name: Lower Fyeshire Pond Dam
District#: 3 County#: 14
Town#: 34 DAM#: 2
River:
IMP Name: Fish Pond
AKA Name:
Basin: 11 Compliance: N
Grant:
Grant Date:
Fish Ladder:

Size Class:
Dam Type:
Purpose:
Year Comp: 0
Struct Height (ft): 9
Hydro Height (ft): 5.1
Drain Area (Sq. mi): 0
Vol. Impoundment (acre-ft): 23.8
Max Impoundment (acre-ft): 46.2
Crest Length (ft): 0
Spill Type:
Spill Length (ft): 0
Spill Capacity (cfs): 0

USGA Quad:
Inspection Reg:
Conditional Letter: UN
Army Phase 1 RPT: N
DCR Phase 1 RPT: N
Latitude: 42.4153
Longitude: -71.64902
Ferc. Lic: N
253 Permit Date:
Crest Public Road:
Crest Public Bridge:
Registered: N

Owner: Town of Bolton
Street: Town Hall - 663 Main St.
Town: Bolton, MA 01740
Phone: (978) 779-3304
Owner type: 20
FAX:
Email:

Caretaker: Town of Bolton
Street: Town Hall - Main St.
Care. Town: Bolton, Ma 01740
Phone: (508) 877-2297
FAX:
Email:

Last_date_Changed: 1/31/2008

Comment:
 JP enter 2/08: Dam falls under DCR jurisdiction as Class II based on T&B 7/18/07 VIF report, subject to possible hazard potential re-classification based on required Phase I inspection.
 Owner updated 12/07 based on Tighe & Bond Ownership Report.

ODSREVIEW:
HC: S Last Reg. Inspection Date: 01/01/1975 Next Reg. Inspection Date: 12/31/1979 Inspection Frequency: 5
Update Confirmation to file DCR Initial: Date: 1/2/08

ORPSTATUS: C JDSTATUS: F DCRPH1Status:
Jurisdictional Status: Y

Department of Conservation and Recreation DAM Detail

National ID: MA01512

DCR Inspector TCF

DCR Date:

Consultant

Reg. Ins. Date

Inspection cond

Inspection Compliance:

Date Report Received:

Date Returned to Owner:

Design

Maint. Level

Emerg Plan

Embank. Sepage

Embank. Cond.

Est. Repair Cost

\$0.00

Concrete. Cond.


Lowlevel Capacity

Outlet Cond.

% Capacity

DAM Condition

Comments



APPENDIX D
DEFINITIONS

COMMON DAM SAFETY DEFINITIONS

For a comprehensive list of dam engineering terminology and definitions refer to 302 CMR10.00 Dam Safety, or other reference published by FERC, Dept. of the Interior Bureau of Reclamation, or FEMA. Please note should discrepancies between definitions exists, those definitions included within 302 CMR 10.00 govern for dams located within the Commonwealth of Massachusetts.

Orientation

Upstream – Shall mean the side of the dam that borders the impoundment.

Downstream – Shall mean the high side of the dam, the side opposite the upstream side.

Right – Shall mean the area to the right when looking in the downstream direction.

Left – Shall mean the area to the left when looking in the downstream direction.

Dam Components

Dam – Shall mean any artificial barrier, including appurtenant works, which impounds or diverts water.

Embankment – Shall mean the fill material, usually earth or rock, placed with sloping sides, such that it forms a permanent barrier that impounds water.

Crest – Shall mean the top of the dam, usually provides a road or path across the dam.

Abutment – Shall mean that part of a valley side against which a dam is constructed. An artificial abutment is sometimes constructed as a concrete gravity section, to take the thrust of an arch dam where there is no suitable natural abutment.

Appurtenant Works – Shall mean structures, either in dams or separate therefrom, including but not be limited to, spillways; reservoirs and their rims; low level outlet works; and water conduits including tunnels, pipelines, or penstocks, either through the dams or their abutments.

Spillway – Shall mean a structure over or through which water flows are discharged. If the flow is controlled by gates or boards, it is a controlled spillway; if the fixed elevation of the spillway crest controls the level of the impoundment, it is an uncontrolled spillway.

Size Classification

(as listed in Commonwealth of Massachusetts, 302 CMR 10.00 *Dam Safety*)

Large – structure with a height greater than 40 feet or a storage capacity greater than 1,000 acre-feet.

Intermediate – structure with a height between 15 and 40 feet or a storage capacity of 50 to 1,000 acre-feet.

Small – structure with a height between 6 and 15 feet and a storage capacity of 15 to 50 acre-feet.

Non-Jurisdictional – structure less than 6 feet in height or having a storage capacity of less than 15 acre-feet.

Hazard Classification

(as listed in Commonwealth of Massachusetts, 302 CMR 10.00 *Dam Safety*)

High Hazard (Class I) – Shall mean dams located where failure will likely cause loss of life and serious damage to home(s), industrial or commercial facilities, important public utilities, main highway(s) or railroad(s).

Significant Hazard (Class II) – Shall mean dams located where failure may cause loss of life and damage to home(s), industrial or commercial facilities, secondary highway(s) or railroad(s), or cause the interruption of the use or service of relatively important facilities.

Low Hazard (Class III) – Dams located where failure may cause minimal property damage to others. Loss of life is not expected.

General

EAP – Emergency Action Plan - Shall mean a predetermined plan of action to be taken to reduce the potential for property damage and/or loss of life in an area affected by an impending dam break.

O & M Manual – Operations and Maintenance Manual; Document identifying routine maintenance and operational procedures under normal and storm conditions.

Normal Pool – Shall mean the elevation of the impoundment during normal operating conditions.

Acre-foot – Shall mean a unit of volumetric measure that would cover one acre to a depth of one foot. It is equal to 43,560 cubic feet. One million U.S. gallons = 3.068 acre feet

Height of Dam – Shall mean the vertical distance from the lowest portion of the natural ground, including any stream channel, along the downstream toe of the dam to the crest of the dam.

Spillway Design Flood (SDF) – Shall mean the flood used in the design of a dam and its appurtenant works particularly for sizing the spillway and outlet works, and for determining maximum temporary storage and height of dam requirements.

Condition Rating

Unsafe - Major structural, operational, and maintenance deficiencies exist under normal operating conditions.

Poor - Significant structural, operation and maintenance deficiencies are clearly recognized for normal loading conditions.

Fair - Significant operational and maintenance deficiencies, no structural deficiencies. Potential deficiencies exist under unusual loading conditions that may realistically occur. Can be used when uncertainties exist as to critical parameters.

Satisfactory - Minor operational and maintenance deficiencies. Infrequent hydrologic events would probably result in deficiencies.

Good - No existing or potential deficiencies recognized. Safe performance is expected under all loading including SDF.